

EXHIBIT 45

0666

WARDDETAIL

ISSUE	VIN	MY	MDL	Model	MFG DATE	PROD YR MON
EXPLODE	KNALN4D74E5[REDACTED]	2014	VG	CADENZA	10/7/2013	2013-10

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

DATE RETAIL	EXT Color	Days @ Defect	Int Color	TM	RO DATE	RO Yr Mon	Miles	PNC
12/3/2013	B3U	405WK		2	2015/1/12	2015-01	1200181630	

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

OP_CD	DESC	N Code	C Code	PARTS	LABOR	SUBLET	TOTAL	PFP
	Panorama Sunroof Sliding Glass Assy, R&R	B21	ZZ4	382.13	166.68	0.00	548.81	81630 3R500

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

PARTNAME	PORT	REGION	DISTRICT	DLR	DLRNAME
----------	------	--------	----------	-----	---------

GLASS ASSY-PANOFPH	EA	02	MA042 MIDWAY MOTORS, INC.		
--------------------	----	----	---------------------------	--	--

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

CITY	ST	CLM TYPE	RO #	Mdl Code	DTC	TIS	CD_OPT	CD_ACC
FRAMING HAM	MA	W	97758 A	E4292			442 10	GIP GP2 CA CF TX9 BA 10 11 18 19 25

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

Date Approved	note
2/17/2015	[S]CONDITION: CUSTOMER STATES SUN-ROOF BLEW OUT CH[S]ECK AND ADVISE CAUSE: BROKEN GLASS. CORRECT[S]ION: 12001 0 VEHICLE CAME INTO SHOP WITH BROKEN[S] SUNROOF GLASS. INSPECTED AND DID NOT SEE ANY S[S]IGNS OF IMPACT. OPENED TECHLINE CASE #T2870300 [S]- WAS ADVISED TO REPLACE GLASS ASSY. REMOVED BR[S]OKEN ASSY, REPLACED AND ADJUSTED GLASS. OPERATE[S]D ASSY SEVERAL TIMES AND WORKS AS DESIGNED. REM[S]OVED FRONT SEATS, SUN SHADE, CLEANED UP INTERIO[S]R AS BEST AS POSSIBLE.

WARDDETAIL

WARDDETAIL

WARDDETAIL

WARDDETAIL

Week

1/16/2015 2/15/2015